New Features Connected Manufacturing

Release version 6.2.0

Content

Introduction	2
Filter reset for Task-Overview-Page	2
Attachments: Operations	3
Adding attachments improved	3
Improved view of attachments: Easy access to related documents	4
Mazak: Spindle loading	6
HAIMER-VIO: Handling of measurement programs	7
Tool measurement: New time stamp logic	8

Introduction

This update brings a host of new features and enhancements to streamline your manufacturing workflow. The focus is on simplifying attachments, improving accessibility to important documents, improving order overview, optimizing tablet usage, and introducing new features for specific machine models.

Filter reset for Task-Overview-Page

On the Task-Overview-Page, selected filters can now be easily reset without having to manually reset each filter. This makes it easier to customize the view and saves valuable time.

Working field 📒 👻	Resources 🔻	NC files 🔻	Task type 🔻 🛛 T	ask state 🔻	Prev. task status 💌	Label 🔻	Period 🔻	Reset all	
Open Completed									

Figure 1 Reset the filter of the Task-Overview-Page

Attachments: Operations

Adding attachments improved

Attachments play an important role in documenting various manufacturing phases. Previously, there were restrictions on adding attachments during certain operations. This update improves handling by allowing documents to be attached at any time, similar to existing functionality at the order, workpiece, and workpiece-assembly levels.

Users can now easily add attachments to tasks without having to switch to "Edit" mode. This ensures smooth workflows that are not restricted by the status of the task or user permissions.

Simply navigate to the desired task to "Attached Files".

× BW	_task_mach_0	1_0223	Show Picklist
General	Schedule	NC files (0)	Attached files (0)
	Drag files h	ere or browse	Max. file size: 200 MB Max. number: 100 files
	No	files have b	een added yet.
		Click on the buttor	below to add files.
		+ A0	ld file(s)

Figure 2 Add attachments

Improved view of attachments: Easy access to related documents

Efficient access to relevant attachments increases productivity. While it was previously possible to add important drawings or documents to workpieces, access to them required a detour via the corresponding workpiece (workpiece, workpiece assembly and/or order) within specific task. This update simplifies the process by providing direct access to attachments associated with workpieces, workpiece assemblies, and orders directly from the task details.

Users can now access attachments linked to workpiece, workpiece assemblies, and orders directly from the operation details. Simply navigate to the desired step and see the associated attachments in the "Attached Files" section.

eneral Schedu	le NC files (1)	Attached files (1)		
Drag f	iles here or browse	Max. file size: 200 MB Max. number: 100 files		
k File Name 🗘	UPLOADED ON 🗘	SIZE 🔶		
Checklist.pdf by Marcus Koppenhöfer	10:51 AM 08/17/2023	54.746 KB 👱 🔋		
kpiece				
FILE NAME 🌲	UPLOADED ON $\hat{\downarrow}$	SIZE 🍦		
Drawing.pdf by Marcus Koppenhöfer	10:52 AM 08/17/2023	781.208 KB		

Figure 3 Assets in the Operation Detail view

Improved job overview: Clearer status differentiation

A clear visual representation is critical to effective order management. In order to improve the distinction between "planned" and "started" orders, icons that are already known from the task overview page are now also integrated on the order overview page.

The Job Summary page now displays recognizable icons and provides a consistent status display for both "Scheduled" and "Started" jobs.



Figure 4 Displays the status of a job that has already been started

Optimized tablet usage for work steps and tools

To facilitate access to settings for tablet users, the "3-point menu" has been fixed to the right of the screen.

Tablet users can now easily access settings via the fixed "3-point menu" on the right side of the screen without scrolling horizontally.



Figure 5 "3-point menu" of a tool

Mazak: Spindle loading

When loading tools via the spindle, the machine operator was previously forced to assign a free slot number to the tool after linking the tool to the machine in order to be able to work with the tool on the machine. This resulted in additional work for the user.

With this release, Connected Manufacturing supports spindle loading in Mazak controllers. As soon as a tool is linked to the machine, not only all previous tool data is written to the machine, but also a magazine location is assigned. Connected Manufacturing checks the status of the magazine and selects the next free slot.

This saves the machine operator the time to check the magazine for free slots and manually write the magazine slot into the tool table. After the linking process, the user can insert the tool directly into the spindle.

This is a special configuration. Therefore, please contact the appropriate support.

HAIMER-VIO: Handling of measurement programs

The update introduced an improvement for the use of measurement programs on Haimer preset devices of the VIO series. From now on, you can easily measure tools with their stored measurement programs and the required values. These values (W1, W2, C, Y) are displayed in the Connected Manufacturing view at the complete tool level and can be edited if you have set up a Haimer VIO device in the Connected Manufacturing settings. You can do this by clicking on the "Edit" option in the context menu (3-point menu) of a complete tool and setting the parameters for an automatic measurement program.

W1 (ANGLE)		UNIT	
18 <mark>1</mark>	\times	Degree	
W2 (ANGLE)		UNIT	
15	\times	Degree	
C (ROTATION STAR	T POINT)	UNIT	
10.1	\times	mm	
Y (TURNING CENTE	R OFFSET)	UNIT	
11	×	Degree	

Figure 6 Parameter input for Haimer-VIO measurement programs

This function is available for all Haimer presets that use measurement programs. Automation of manual tool presetting steps improves process safety and ease of use.

Tool measurement: New time stamp logic

For the details of the complete tool, the "measurement time" is updated immediately when tool values (radius, length, corner radius and/or their correction values) are changed.

Until now, the timestamp had only been updated in two cases:

- 1. The readings came from a preset or
- 2. The tool was measured on a machine for the first time.

The new logic always shows when the values were last changed.

Measurement date & time	08/14/2023 01:40 PM			
	ACTUAL	NOMINAL	TOLERANCE RANGE	CORRECTION
Radius	5.010 mm	5.000 mm	-0.200/+0.200 mm	
Length	92.000 mm	90.000 mm	-8.000/+9.900 mm	
Corner radius	1.000 mm			

Figure 7: Measurement data of a tool with the indication of the measurement time